St. Luke's Episcopal Church 200 East Broadway Granville Licking County Ohio HABS No. 0-400

HABS OHIO 45-GRAN

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Eastern Office, Division of Design and Construction
120 South Third Street
Philadelphia 6, Pennsylvania

HISTORIC AMERICAN BUILDINGS SURVEY

US BRAN.

ST. LUKE'S EPISCOPAL CHURCH

Address:

200 East Broadway, Granville, Licking County, Ohio.

Present Owner:

St. Luke's Episcopal Parish, Granville, Ohio.

Present Occupant:

St. Luke's Episcopal Parish.

Present Use:

Church.

Brief Statement of Significance:

This Greek Revival style church, erected in 1837,

was designed by Benjamin Morgan.

PART I. HISTORICAL INFORMATION

A. Physical History

- 1. Original and subsequent owners: Continuously owned by St. Luke's Episcopal Parish.
- 2. Date of erection: 1837, according to plaque before entrance.
- 3. Architect: Benjamin Morgan "drew plans for building including balcony and pews". Minard Lafever of New York "designed the interior". See: (1) January 1948 issue of Museum Echoes, Ohio State Archaeological and Historical Society; (2) page 45, Early Homes of Ohio by I. T. Frary.
- 4. Original plans, construction etc.: None. Cost \$7,000.00 with furniture and organ. / See History of Licking County, N. N. Hill, Jr. 1881.
- 5. Notes on alterations and additions: Minor restoration by Colonial Dames of Cincinnati within the past 15 years, including the stone steps, side lamps and iron fence enclosing yard, and painting of the blue and ivory ceiling.
- 6. Important old views and references:

Views: Page 190 Early Homes of Ohio, by I. T. Frary.

References: January 1948 issue of <u>Museum Echoes</u>, Ohio State Archaeological and Historical Society.

<u>History of Licking County</u>, N. N. Hill, Jr. 1881.

B. Historical Events Connected with the Structure: Consecrated July 15, 1838. Erected by parish of 19 members, after initial contribution of \$2,500.00 by Sherlock Mowrer.

Partly supported by a Ladies Seminary connected with it. No regular preaching 1873-1881, according to <u>History of Licking</u> County, N. N. Hill, Jr. 1881.

Some restoration in past 15 years by the Colonial Dames of Cincinnati, including the stone steps, side lamps and iron fence enclosing yard, and painting of the blue and ivory ceiling.—January 1948 issue of Museum Echoes of the Ohio State Archaeological and Historical Society.

Prepared by Perry E. Borchers
June 1959

PART II. ARCHITECTURAL INFORMATION

- A. General Statement
 - 1. Architectural Character: This building is an excellent example of Greek Revival design. The interior designing is credited to Minard LaFever of New York.
 - 2. Condition of Fabric: Excellent.
- B. Technical Description of Exterior
 - 1. Overall dimensions: One story with balcony; 42'-7" by 64'-1", rectangular structure.
 - 2. Foundations: Stone.
 - 3. Wall construction: Wood frame. Wood imitates stone jointing on front, and becomes regular clapboard on side.
 - 4. Chimneys: Small chimney to rear.
 - 5. Openings
 - a. Doorways and doors: Wood with Greek Revival trim.
 - b. Windows and shutters: Interior wood shutters.
 - 6. Roof
 - a. Shape, covering: Pitched roof with asphalt shingles.
 - b. Cornice, eaves: Wood, Greek Revival detail.
 - c. Dormers, cupolas: No dormers; wood cupola.
- C. Technical Description of Interiors
 - Floor Plans: Almost entirely occupied by main room. Very tiny vestry and office for Pastor on each side of recessed

altar. Recessed porch with entrances to each side, and balcony stairway.

- 2. Stairways: Stairways to balcony of main room and to basement Sunday School are wood.
- Flooring: Wood.
- 4. Wall and ceiling finish: Plaster. There is a very ornate plaster centerpiece of ceiling, from which hangs a brass chandelier.
- 5. Doorways and doors: Wood.
- 6. Trim: Wood, Greek Revival detail.
- 7. Hardware: Old iron fixtures converted to modern electric lighting.
- 8. Lighting: Electricity in old lamps.
- 9. Heating: Central heating.

D. Site

- 1. General setting and orientation: Set slightly back from main street; building faces north.
- 2. Enclosures: Fenced yard.
- 3. Outbuildings: None.
- 4. Walks, driveways etc.: Concrete walk to stone entrance steps.
- 5. Landscaping, gardens etc.: Natural.

Prepared by Perry E. Borchers June 1959 Addendum to:
ST. LUKE'S EPISCOPAL CHURCH
200 E. Broadway
Granville
Licking County
Ohio

HABS No. OH-400

HABS OHIO US-GREN

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey National Park Service Department of the Interior Washington, DC 20013-7127

HARDS OHIO H5-GRAM

HISTORIC AMERICAN BUILDINGS SURVEY

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Addendum to:
ST. LUKE'S EPISCOPAL CHURCH
200 E. Broadway
Granville
Licking County
Ohio

HABS No. OH-400

Data pages 1 through 3 were previously transmitted to the Library of Congress. This is data page 4.

INVENTORY OF PHOTOGRAMMETRIC IMAGES

The glass photogrammetric plates listed below are not reproducible except with special permission. However, reference prints and film copy negatives have been made from the plates indicated by an asterisk (*) and are included in the Library of Congress collection of formal HABS/HAER photographs.

12 4" x 6" glass plate diapositives (6 stereopairs), and

4" x 6" glass plate negatives (5 stereopairs) produced by Perry E. Borchers of the Ohio State University in 1958.

One survey control contact print per plate; survey control information for each plate.

LC-HABS-GS07-T-935-400L *

NORTH (FRONT) ELEVATION

(Negative)

LC-HABS-GS07-T-935-400R

NORTH (FRONT) ELEVATION

(Negative)

Left and right overlap: 90%

LC-HABS-GS07-T-935-401L

NW CORNER

(Negative)

LC-HABS-GS07-T-935-401R *

NW CORNER

(Negative)

Left and right overlap: 90%

ST. LUKE'S EPISCOPAL CHURCH HABS No. OH-400 Data (Page 5)

LC-HABS-GS07-T-935-402L

SOUTH (REAR) ELEVATION

(Negative)

LC-HABS-GS07-T-935-402R *

SOUTH (REAR) ELEVATION

(Negative)

Left and right overlap: 85%

LC-HABS-GS07-T-935-403L

SE CORNER

(Negative)

LC-HABS-GS07-T-935-403R *

SE CORNER (Negative)

Left and right overlap: 85%

LC-HABS-GS07-T-935-404L

NE CORNER

(Negative)

LC-HABS-GS07-T-935-404R *

NE CORNER

(Negative)

Left and right overlap: 95%

LC-HABS-GS07-T-935-405L *

NORTH PORCH

(Negative)

LC-HABS-GS07-T-935-405R*

NORTH PORCH

(Negative)

Left and right overlap: 95%

LC-HABS-GS07-T-935-406L *

INTERIOR, ALTAR

(Negative)

LC-HABS-GS07-T-935-406R

INTERIOR, ALTAR

(Negative)

Left and right overlap: 90%

ST. LUKE'S EPISCOPAL CHURCH HABS No. OH-400 Data (Page 6)

LC-HABS-GS07-T-935-407L *

ALTAR AND CEILING FROM BALCONY

(Diapositive enlargement)

LC-HABS-GS07-T-935-407R

ALTAR AND CEILING FROM BALCONY

(Diapositive enlargement)

Left and right overlap: 90%

LC-HABS-GS07-T-935-408L

INTERIOR, BALCONY

(Diapositive enlargement)

LC-HABS-GS07-T-935-408R *

INTERIOR, BALCONY

(Diapositive enlargement)

Left and right overlap: 95%

LC-HABS-GS07-T-935-409L *

CEILING FROM BALCONY

(Diapositive enlargement)

LC-HABS-GS07-T-935-409R

CEILING FRON BALCONY

(Diapositive enlargement)

Left and right overlap: 95%

LC-HABS-GS07-T-935-410L *

CEILING ORNAMENT

(Diapositive enlargement)

LC-HABS-GS07-T-935-410R

CEILING ORNAMENT

(Diapositive enlargement)

Left and right overlap: 90%

PROJECT INFORMATION STATEMENT

Photogrammetric images were incorporated into the HABS/HAER collections in the summers of 1985 and 1986. Inventories of the images were compiled and filed as data pages for each structure recorded. Since the glass photogrammetric plates are not reproducible except with special permission, a reference print and film copy negative were made from one plate of each stereopair and from the most informative plates in sequential sets. The reference prints and copy negatives were then incorporated into the formal HABS/HAER photograph collections.

ST. LUKE'S EPISCOPAL CHURCH HABS No. OH-400 Data (Page 7)

The Photogrammetric Images Project was a cooperative endeavor between the HABS/HAER Division of the National Park Service and the Prints and Photographs Division of the Library of Congress. The reference prints and film copy negatives of the original plates were made by the Library of Congress Photoduplication Service with funds provided by the Library of Congress Flat Film Preservation Fund. Additional reproductions were made by HABS/HAER. The project was supervised by HABS/HAER Architect John A. Burns, AIA, and completed by HABS Historians Jeanne C. Lawrence (University of London) in 1985 and Caroline R. Alderson (Columbia University) in 1986.